



# FAA

## Aviation Safety

---

---

### Memorandum

Date:

To: Derek Honda, Directives Management, AFB-120

From: Jackie Black, Manager, Aircraft Maintenance Division AFS-300

Prepared by: Patricia K Williams, Branch Manager, AFS-340

Subject: POR Change, Advisory Circular (AC) 43-207, dated 12/26/2002

---

---

AC 43-207 Correlation, Operation, Design, Modification of Turbofan/Jet Engine Test Cells, was developed in consortium with the Engine Certification Office, based on 1999 Society Of Automotive Engineer (SAE) data.

With the future of flight standards transformation and the evolutionary enhancements made towards engine analysis, we find this advisory circular to be outdated. This AC will require a major revision to become relevant to today's technology and the expertise is within the Aircraft Certification Office.

The Aircraft Maintenance Division believes the logical office to accomplish the revision and assume responsibility as the POR would be the AFS-100, Aircraft Evaluation, led by Jeffrey Phipps.

Please change the POR from AFS-340 to AFS-100.

#### **Approval/Disapproval**

Approve: \_\_\_\_\_

Disapprove: \_\_\_\_\_

---

Phipps Jeffery  
Manager, Aircraft Evaluation Division  
AFS-100

---

Date

