

Phase 4 Gate Prior to Proving Flights Requirements

The following **Phase 4 Gate Prior to Proving Flights** Gate 3 requirements must be met in order to proceed to Proving Flights:

- Show Cause Order or Final Order received from DOT NEPA Documentation Complete
- Aircraft conformity evaluation complete
- Evacuation Demonstration successfully completed (if required)
- Ditching Demonstration successfully completed (if required)
- Fatigue Education and Awareness Training (FEAT) and Fatigue Risk Management Program (FRMP) Approved
- Weight and Balance Control Program (WBCP) Concurrence Received
- Draft Operations Specifications generated (including A317 and A319)
- Letter of Authorization Issued