

FAA-H-8083-15B
Instrument Flying Handbook
Updated July 25, 2013

Errata as of December 21, 2012

1. In Figure 5-3 on page 5-4, the “1,000 ft. pointer” label should be changed to read “100 ft. pointer,” the “100 ft. pointer” label should be changed to read “10,000 ft. pointer,” and the “10,000 ft. pointer” label should be changed to read “1,000 ft. pointer.”

Errata as of July 25, 2013

1. In the second-to-last sentence of the second paragraph in the right column of page 9-11, the VOR CDI deviation value should be changed from “12°” to “10°”.