ORDER

## DEPARTMENT OF TRANSPORTATION FEDERAL AVIATION ADMINISTRATION

GREAT LAKES REGION

GL 6980.17

8/15/73

62.5 KVA ENGINE GENERATORS, J. R. HOLLINGSWORTH COMPANY, CONTRACT FA-2674

- 1. <u>PURPOSE</u>. This Order is to advise the field offices of a discrepancy in the instruction books and the fusing of the immersion heater circuits of the subject engine generators and to direct corrective action.
- 2. <u>DISTRIBUTION</u>. This Order is distributed to the Airway Facilities Division, Branch level and above, and to all Airway Facilities field offices.
- 3. CANCELLATION. Order CE SM 6980.14 is cancelled.
- BACKGROUND. This office has information from Washington that during factory inspection it became apparent the 1500-watt immersion heaters being installed on the subject plants were inadequate. Therefore, 2180-watt heaters were substituted and supplied with MDF-8 fuses. These fuses proved to be inadequate during field operation.
- 5. ACTION. Sector Offices shall replace the MDF-8 fuses with a similar type 15-ampere fuse and shall correct the instruction manuals to reflect the type heater and fuses installed.

ALAN H. GLASS

Chief, Airway Facilities Division

Distribution: RAF-3; FAF-0 (Normal)

Initiated By: AGL-445