

SAFETY ALERT

Date: March 18, 2025

To: Users of the Aeronautical Information Services 28 Day NASR Subscriber Files

From: Aeronautical Information Services, AJV-A

Subject: FIX - DUCBA

Effective 17 APR 2025, in the FIX.txt, FIX_BASE.csv, FIX_CHRT.csv, and FIX_NAV.csv of the 28-Day NASR Subscription; ENROUTE LOW and CONTROLLER LOW were omitted and the incorrect Fix Makeup Bearing was listed. The correct bearing and charting for DUCBA should be as shown below. DUCBA will be corrected for the 12 JUNE 2025 28-Day NASR subscription.

FIX.txt

				State			
Fix Id	Fix Use	Fix Lat	Fix Lon	Name	ARTCC	Fix/Nav Makeup	Charting Types
DUCBA	REP-PT	48-10-39.72N	104-36-55.90W	MONTANA	ZLC	ISN*D*254.86/35	IAP
							CONTROLLER LOW
							ENROUTE LOW

FIX_BASE.csv

FIX_ID	STATE_CODE	FIX_USE_CODE	CHARTS
DUCBA	MT	RP	IAP, CONTROLLER LOW, ENROUTE LOW

FIX_CHRT.csv

FIX_ID	STATE_CODE	CHARTING_TYPE_DESC		
DUCBA	MT	IAP		
DUCBA	MT	CONTROLLER LOW		
DUCBA	MT	ENROUTE LOW		

FIX_NAV.csv

FIX_ID	STATE_CODE	NAV_ID	NAV_TYPE	BEARING	DISTANCE
DUCBA	MT	ISN	VOR/DME	254.86	35