



Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: 008C86F1B3B141DDB183E54201B4139F	APWS Project ID: 8A368F977DD8441DAAA803148082C6AA
Procedure: VOR-A AMDT 5A		Enroute: NO	Specialist: Heiderstadt, Nicholas		Agreement Number:
Airport ID: KAJO			Airport City: CORONA		State: CA
Facility ID: PDZ	Facility Type: VORTAC	Flight Inspection Remark Type:			
Procedure Comments: P-NOTAM, ADD DME NOTE ACTIVE DATA USED CONTACT ROBERT HAMILTON 405-954-4608 QUALITY 41 CHECKED QUALITY 13 CHECKED					

VOR-A
CORONA MUNI (AJO)




MISSED APPROACH: Climbing right turn to 4700 direct PDZ VORTAC then on PDZ VORTAC R-078 to AZARR/5 DME and hold, continue climb-in-hold to 4700.

AWOS-3PT 132.175	SOCAL APP CON 135.4 377.125	UNICOM 122.7 (CTAF) ①
----------------------------	---------------------------------------	---------------------------------



OLD

A1369

 $\Delta 3110 \pm$

A 845

•1853

1900.


A1677

A1489

Δ1586

Δ 4100

3000

[illegible]

CATEGORY	A	B	C	D	FAF to MAP 3.6 NM					
CIRCLING	1660-1¼ 1127 (1200-1¼)	1660-1½ 1127 (1200-1½)	NA		Knots	60	90	120	150	180
					Min:Sec	3:36	2:24	1:48	1:26	1:12