

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 08/07/2025	APWS Task ID: 02C6A1EDA5ED4D1C914E0F49E3002427	APWS Project ID: C4B3E35784D4437281DDCA8C0BC913A2
Procedure: FIX EBONY 9 ME US		Enroute: NO	Specialist: Bruce, Richard		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			

Procedure Comments:

FIX MAKE-UP: REMOVED SAINT JOHN (YSJ) VOR/DME AND MILLINOCKET (MLT) VOR/DME.

CONTACT RAKE MCGRAW, AJV-A422, (405) 954-8711.

