Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 06/15/2023	APWS Task ID: 0CC774543D08430D81E23DD8AF8ACB81	APWS Project ID: C760094F132E4DF2B8077E812DC0C4FE
		Enroute: NO	Specialist: Martinelli, Tara		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			

**Procedure Comments:** 

RBLEW, CA REV 1

FIX INQUIRY/UPDATED AS NEEDED. NOT ALL DATABASES ARE CURRENT. SOME FIXES UPDATED TO ENSURE NASR, NFDC AND IFP FIX ARE CURRENT AND ALIGNED.

CRTER, CA REV 1
COALDALE (OAL) VORTAV, NV REV 27
DAYMN, NV REV 1
HERSH, UT REV 1
HNNRY, CA REV 1
ITKIC, AK REV 3
KOROR NDB/DME, PW REV 4
MARVN, AK REV 1

4/10/2023: THIS IS A CORRECTED COPY OF THE FORMS APPROVED ON 03/30/2023.

FIX HERSH 8260-2: CHANGED CONTROLLER LOW TO CONTROLLER HIGH.

CONTACT DAVE DANNER: AJV-A442, 405-954-5077

OVALITY 4 CHECKED

Digitally signed by

DAVID DANNER

Apr 13, 2023