

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: 183D311DF7994DC4B4747B5C570FC3AA	APWS Project ID: B475F040E1EF487A9B7570AAF21F5AF9
Procedure: RNAV (GPS) RWY 5 ORIG		Enroute: NO	Specialist: Smith, Rodney		Agreement Number:
Airport ID: E25			Airport City: WICKENBURG		State: AZ
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: ACTIVE AIRPORT DATA USED. VFR TO IFR AIRPORT. POC: KYLE THOMPSON 405-954-2135 QUALITY 29 CHECKED QUALITY 8 CHECKED					




WAAS CH 82747 W05A	APP CRS 018°	Rwy Idg 6101 TDZE 2379 APT Elev 2379
--------------------------	-----------------	--

RNAV (GPS) RWY 5

WICKENBURG MUNI (KE25)

RNP APCH - GPS.	MISSED APPROACH: CLIMB TO 5900 THEN CLIMBING RIGHT TURN TO 7100 DIRECT ROWLA AND HOLD.
RWY 5 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, PROCEDURE NA. STRAIGHT-IN AND CIRCLING RWY 5 NA AT NIGHT.	

PROTOTYPE-NOT FOR NAVIGATION



FASOL				5900	7100	ROWLA
CATEGORY	A		B		C	D
LP	2980-1 601				2980-1 3/4 601	
LNAV	3220-1 841		3220-1 1/4 841		3220-2 1/2 841	
CIRCLING	3220-1 1/4 841				3500-3 1121	3880-3 1501