

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 07/11/2024	APWS Task ID: 277AE47CAFC544CC959E7047E9FF42F2	APWS Project ID: 3573AB57F0CA4D7EAA6C6247A410EFC4
Procedure: ILS OR LOC RWY 27 AMDT 10D		Enroute: NO	Specialist: Boone-walt, Rose		Agreement Number:
Airport ID: KTLH			Airport City: TALLAHASSEE		State: FL
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021, Subject: Guidance for Procedural Changes Requiring Flight Inspection/Validation CONTACT: CASEY HILL AJV-A412 LEAD: 405.945.0624					

QUALITY
33
CHECKED



QUALITY
30
CHECKED

LOC/DME I-PLQ	APP CRS	Rwy Idg	8000
111.9	274°	TDZE	58
Chan 56		Apt Elev	83

OLD

ILS or LOC RWY 27
TALLAHASSEE INTL (TLH)

DME required.		ALSf-2	MISSED APPROACH: Climb to 2000 then climbing right turn to 4000 on heading 092° and on SZW VORTAC R-140 to GACED INT/SZW 12.4 DME and hold, continue climb-in-hold to 4000.		
ATIS	TALLAHASSEE APP CON ★	TALLAHASSEE TOWER ★	GND CON	CLNC DEL	UNICOM
119.45 239.25	135.8 317.4	118.7(CTAF) 257.8	121.9 348.6	126.65 275.8	123.075



CATEGORY		A	B	C	D	E
S-ILS 27		258/18 200 (200-1/2)				
S-LOC 27		800/24 742 (800-1/2)	800/40 742 (800-3/4)	800-1 3/4 742 (800-1 3/4)		
CIRCLING		800-1 717 (800-1)	800-1 1/4 717 (800-1 1/4)	800-2 717 (800-2)	800-2 1/4 717 (800-2 1/4)	1000-3 917 (1000-3)
		SPADD FIX MINIMUMS				
S-LOC 27		420/24	362 (400-1/2)	420/35	362 (400-3/4)	
CIRCLING		580-1 497 (500-1)	600-1 517 (600-1)	640-1 1/2 557 (600-1 1/2)	800-2 1/4 717 (800-2 1/4)	1000-3 917 (1000-3)

