

Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP	Estimated Chart Date: 10/02/2025	APWS Task ID: 2D8AE475294C443298CBB2C4C591BBA7	APWS Project ID: 21063D4ECA9742F89E33324E2FDEBAEF
Procedure: RNAV (GPS) RWY 14 AMDT 1A		Enroute: NO	Specialist: Davis, Patrick		Agreement Number:
Airport ID: 3D2			Airport City: EPHRAIM		State: WI
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: USED DATA PENDING 4/17/25 EFFECTIVE DATE. 28-DAY REVIEW #27675 FINDING FROM NEW OIS SURVEY: 20:1 VISUAL AREA PENETRATION TO RWY 14. ADDED DATA NOTES PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION CLEAR NOTAM FDC 5/6197. POC: ERIC SUSKI, AJV-A330 MANAGER, 405-954-7331 05/23/2025 QUALITY 14 CHECKED QUALITY 38 CHECKED					

APP CRS
140°

Rwy Idg
2697

TDZE
763

Apt Elev
763

OLD

RNAV (GPS) RWY 14

EPHRAIM/GIBALTAR (3D2)

RNP APCH - GPS.

Rwy 14 helicopter visibility reduction below ¾ SM NA.

MISSED APPROACH: Climbing right turn to 3000 direct MNM DME and hold.

AWOS-3PT
124.175

GREEN BAY APP CON★
120.3 338.2

UNICOM
123.0 (CTAF) 0

