

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 04/17/2025	APWS Task ID: 2DFC0809B7064A54AF33299A84553ECA	APWS Project ID: 4512857C829A4191AC0478371C47316D
Procedure: RNAV (GPS) RWY 10R AMDT 2		Enroute: NO	Specialist: Bruce, Richard		Agreement Number:
Airport ID: KMRY			Airport City: MONTEREY		State: CA
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: ADDED NEW LPV LINE OF MINIMA TO 200 HAT WITH MISSED CLIMB GRADIENT. ACTIVE DATA USED FOR KMRY AIRPORT AND RUNWAYS. NEW CRC REMAINDER: 01D0DB97. CONTACT RAKE MCGRAW, AJV-A422, (405) 954-8711. QUALITY 21 CHECKED QUALITY 9 CHECKED BEGUE					

FIPC BASIC FORM							
PROCEDURE: RNAV (GPS) RWY 10R AMDT 2			AIRPORT NAME: MONTEREY RGNL		AIRPORT ID: KMRY	SPECIAL CONTROL NO: SG-12-273-24	
FAC ID: KMRY10R.02		CITY: MONTEREY			ST: CA	ORIG CHART DATE: 04/17/2025	
DFL TYPE: PROC/S	THIRD PARTY: ☐ YES	EST. TIME ON SITE: 0.4	REIMB. NUMBER:		PTS TASK ID: 2DFC0809B7064A54AF33299A84553ECA		
PREFLIGHT NOTES							
REVIEWER: troy e devine					DATE: 02/18/2025		
COMMENTS:					CHECK ONE:		
					☒ FLT CK REQ ☐ NFCR ☐ REJECT		
							YES
					CPV COMPLETE?		X
PROCEDURE RESULTS							
INSPECTION DATE: 02/18/2025		CREW #: VN502	N #: N72	INSTRUMENT PROCEDURE STATUS: ☒ SAT ☐ SAT W/CHANGES ☐ UNSAT		ARINC CODING: ☒ SAT ☐ SAT/GOLD ☐ UNSAT	
FLIGHT INSPECTOR SIGNATURE: troy e devine @ 02/18/2025 19:02			PRINTED NAME: DEVINE, TROY ELLEN			NOTAM INITIATED? ☐ YES ☒ NO	
FLIGHT INSPECTOR REMARKS: Monterey RGNL Monterey CA, RNAV (GPS) RWY 10 R AMDT 2 New CRC - SAT Non standard CG on LPV missed, LPV mins added.. Runway survey - SAT							
IN-FLIGHT OBSTACLE REPORT							
OBSTRUCTION ID #:	COORDINATES OR LOCATION:		GNSS ALTITUDE (MSL):		BAROMETRIC ALTITUDE (MSL):		HEIGHT ABOVE GROUND LEVEL:

MONTEREY, CALIFORNIA

AL-271 (FAA)


FIG

WAAS CH 69602 W10A	APP CRS 098°	Rwy Idg TDZE Apt Elev	7000 198 257
--	------------------------	-----------------------------	---

RNAV (GPS) RWY 10R MONTEREY RGNL (MRY)

RNP APCH - GPS.	MALS	MISSED APPROACH: Climb to 1000 then climbing left turn to 5000 direct SNS VORTAC and hold, continue climb-in-hold to 5000. * Missed approach requires minimum climb of 387 feet per NM to 1700.
⚠ For uncompensated Baro-VNAV systems, LNAV/VNAV NA below 2°C or above 54°C. Circling NA south of Rwy 10R and 28L. For inop ALS, increase LPV all Cats visibility to 1½ SM and LNAV Cat C/D visibility to 2½ SM. * RVR 1800 authorized with use of FD or AP or HUD to DA.		

ATIS 119.25	NORCAL APP CON 133.0 251.15 (001°-135°) 127.15 307.125 (136°-360°)	MONTEREY TOWER ★ 118.4 (CTAF) 257.8	GND CON 120.875 348.6	CLNC DEL 135.45	UNICOM 122.95
-----------------------	--	--	---------------------------------	---------------------------	-------------------------



ZEBED		1000	5000	SNS
4 NM Holding Pattern				
6000 2600		278°	098°	
GP 3.00° TCH 45				
MINCK		1700	2.4 NM to RWY 10R	RWY 10R
3.7 NM		2.3 NM	2.4 NM	
CATEGORY	A	B	C	D
LPV DA *		398/24	200 (200-½)	
LPV DA		677/50	479 (500-1)	
LNAV/VNAV DA		754/60	556 (500-1¼)	
LNAV MDA	980/24 782 (800-½)	980/40 782 (800-¾)	980-1¾ 782 (800-1¾)	
CIRCLING	980-1 723 (800-1)	980-1¼ 723 (800-1¼)	1280-3 1023 (1100-3)	NA

1.4% UP 3503 X 60 7175 X 150 28L

TWR 301

MIRL Rwy 10L-28R
HIRL Rwy 10R-28L
REIL Rwy 28L
REIL Rwy 10L and 28R

AUTOMATED AL-271 RNAV (GPS) RWY 10R
AUTOMATED AL-271 RNAV (GPS) RWY 10R

SW-2
 12-19-24
 COMPILER: JUN
 REVIEWER:
 DBL CHKR:
 EFF. DATE: FIG

MONTEREY, CALIFORNIA

Amdt 2 FIG

36°35'N-121°51'W

MONTEREY RGNL (MRY)
RNAV (GPS) RWY 10R


WAAS CH 69602 W10A	APP CRS 098°	Rwy Idg TDZE 198 Apt Elev 257
--	------------------------	---

OLD

RNAV (GPS) RWY 10R
MONTEREY RGNL (MRY)

RNP APCH.	MALSR	MISSED APPROACH: Climb to 1000 then climbing left turn to 5000 direct SNS VORTAC and hold, continue climb-in-hold to 5000.
⚠ Circling NA south of Rwy 10R and 28L. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below 0°C or above 54°C. For inop ALS, increase LPV visibility all Cats to 1½ SM, LNAV/VNAV visibility all Cats and LNAV Cat C/D to 2½ SM.	AS	


ATIS 119.25	NORCAL APP CON 133.0 251.15 (001°-135°) 127.15 307.125 (136°-360°)	MONTEREY TOWER ★ 118.4 (CTAF) 257.8	GND CON 120.875 348.6	CLNC DEL 135.45	UNICOM 122.95
-----------------------	--	--	---------------------------------	---------------------------	-------------------------




4 NM Holding Pattern		ZEBED	MINCK	1000	5000	SNS
6000 2600		← 278° 098° →	098°	*2.4 NM to RWY 10R	*LNAV only	
GP 3.00° TCH 45		1700				
		3.7 NM	2.3 NM	2.4 NM		
CATEGORY	A	B	C	D		
LPV DA	718-1½		520 (500-1½)			
LNAV/VNAV DA	789-1¾		591 (600-1¾)			
LNAV MDA	980/24 782 (800-½)	980/40 782 (800-¾)	980-1¾ 782 (800-1¾)			
CIRCLING	980-1 723 (800-1)	980-1¼ 723 (800-1¼)	1280-3 1023 (1100-3)	NA		
						MIRL Rwy 10L-28R HIRL Rwy 10R-28L REIL Rwy 28L REIL Rwy 10L and 28R


SW-2, 05 SEP 2024 to 03 OCT 2024

SW-2, 05 SEP 2024 to 03 OCT 2024







MONTEREY RGNL (MRY)
MONTEREY, CALIFORNIA
RNAV (GPS) RWY 10R, AMDT 2
100,000
LPV 398 DA, MISSED CG



MONTEREY RGNL (MRY)
MONTEREY, CALIFORNIA
RNAV (GPS) RWY 10R, AMDT 2
100,000
LPV 677 DA





MONTEREY RGNL (MRY)
MONTEREY, CALIFORNIA
RNAV (GPS) RWY 10R, AMDT 2
100,000
LNAV/VNAV

LNAV/VNAV
TREE (325) 06-096560

LNAV/VNAV Missed Penetration
TREE (832) 06-107130

Missed Level Surface
AAO (1326)

MONTEREY RGNL (MRY)
MONTEREY, CALIFORNIA
RNAV (GPS) RWY 10R, AMDT 2
100,000
LNAV, CIRCLING

