

FEDERAL AVIATION ADMINISTRATION  
FLIGHT STANDARDS SERVICE  
TRANSMITTAL OF AIRWAYS/ROUTES DATA RECORD

AIRWAY NO or ROUTE

J96

ROUTINE or DOCKET NO

<u>FROM</u>	<u>STATE</u>	<u>FB/FO</u>	<u>TO</u>	<u>STATE</u>	<u>FB/FO</u>	<u>RNP</u>	<u>LEG TYPE</u>
CIMARRON (CIM) VORTAC	NM		GARDEN CITY (GCK) VORTAC	KS			

<u>OBSTRUCTION</u>	<u>COORDINATES</u>	<u>ELEV MSL</u>	<u>CONT OBS</u>	<u>AC</u>	<u>ROC</u>	<u>ADJUSTMENTS</u>
--------------------	--------------------	-----------------	-----------------	-----------	------------	--------------------

<u>MRA</u>	<u>MOCA</u>	<u>PUB</u>	<u>MAA</u>	<u>D/D/I</u>	<u>MEA (1)</u>	<u>DIRECTION (1)</u>	<u>MEA (2)</u>	<u>DIRECTION (2)</u>	<u>GNSS MEA</u>
------------	-------------	------------	------------	--------------	----------------	----------------------	----------------	----------------------	-----------------

<u>COP</u>	<u>FIX MRA</u>	<u>FIX MCA</u>	<u>MTA</u>
------------	----------------	----------------	------------

SEGMENT REMARKS

CHART: SEGMENT UNUSABLE

CHANGES-REASONS

SEGMENT UNUSABLE - DUE TO FLIGHT CHECK REPORT 12/21/2020 CIM VOR UNUSABLE 045-055 BYD 40NM.

DECLARATION OF EXCLUSION: THE FAA HAS REVIEWED THE ABOVE REFERENCED PROPOSED ACTION AND IT HAS BEEN DETERMINED, BY THE UNDERSIGNED, TO BE CATEGORICALLY EXCLUDED FROM FURTHER ENVIRONMENTAL DOCUMENTATION ACCORDING TO FAA ORDER 1050.1F, "ENVIRONMENTAL IMPACTS: POLICIES AND PROCEDURES." THE IMPLEMENTATION OF THIS ACTION WILL NOT RESULT IN ANY EXTRAORDINARY CIRCUMSTANCES IN ACCORDANCE WITH FAA ORDER 1050.1F.

<u>FLIGHT CHECK</u>	<u>DATE</u>	<u>OFFICE</u>	<u>NAME</u>
PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.			

  

<u>APPROVED</u>	<u>DATE</u>	<u>OFFICE</u>	<u>TITLE</u>	<u>NAME</u>	<u>Digitally signed by</u>	<u>Digitally signed by</u>
	10/23/2025	AJV-A4	MANAGER	ALLAN WILL	<i>DAVID DANNER</i>	<i>DAVID DANNER</i>
					May 14, 2025	May 14, 2025

