



|   |                         |                                |                                     |   |  |
|---|-------------------------|--------------------------------|-------------------------------------|---|--|
| Flight Procedures Cover Page  | Task Action:<br>P-NOTAM | Task Type:<br>IAP              | Estimated Chart Date:<br>11/30/2023 | APWS Task ID:<br>3841B75AB29C4021B60D0EC3890788F9 | APWS Project ID:<br>1B89B673249642528922B0F9E1714B56 |
| Procedure:<br>APPROACH RNAV GPS RWY 19, AMDT 1A   |                         | Enroute:<br>NO                 | Specialist:<br>Zeder, Joseph        |   | Agreement Number:                                    |
| Airport ID:<br>KFLO   |                         |                                | Airport City:<br>FLORENCE           |   | State:<br>SC   |
| Facility ID:  | Facility Type:          | Flight Inspection Remark Type: |                                     |   |  |
| <div>Procedure Comments:<br/>POC: CASIMIR TABAKA PH 405-954-7931</div> <div>PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION VALIDATION.</div> <div>NOTAM 3/2531</div> <div>09/14/2023</div> <div>QUALITY<br/>9<br/>CHECKED<br/>BEGUE</div> <div>QUALITY<br/>14<br/>CHECKED</div> |                         |                                |                                     |   |  |









KFLO, SC  
RNAV (GPS) RWY 19 AMDT 1A  
MISSED APPROACH  
1:100K  
LNAV

\_FRACK [UD]

LNAV \_HOBEN 7:1 Excluded Obs TOWER (948)  
45-000081

LNAV KFLO:RW19:AER 7:1 Excluded Obs TOWER (383)  
45-021196

LNAV \_FRACK to \_HOBEN TOWER (383)  
45-021196

LNAV \_HOBEN to KFLO:RW19:AER TANK (300)  
45-000716

MENGY

\_MENGY [UD]

\_GOCEL [UD]

RW19

RW09 KFLO

RW27

Missed Level Surface TOWER (598)  
45-000979

\_PAIS [UD] PAIS

NUT  
45-01