

Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP	Estimated Chart Date: 09/05/2024	APWS Task ID: 451570BA3830487CAA0AC319956A13A8	APWS Project ID: 1D61C82B16924D139B11D8F35E7B13BE
Procedure: ILS OR LOC RWY 10 AMDT 0A		Enroute: NO	Specialist: Smart, Phillip		Agreement Number:
Airport ID: KTVK			Airport City: TRAVERSE CITY		State: MI
Facility ID: TVC	Facility Type: ILS	Flight Inspection Remark Type:			
Procedure Comments: RENAME THE PFAF FROM CEKUK TO RIFKI Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021 Guidance for Procedural Changes Requiring Flight Inspection/Validation CONTACT MR. JOHN BORDY AT 405-954-0980. Federal Aviation Administration QUALITY 9 CHECKED BEGUE QUALITY 34 CHECKED					

