



Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 10/02/2025	APWS Task ID: 4ADE6D36FEE94116ABCD31DB1D30AD99	APWS Project ID: 05C92B1E04F04BA09A5FC466F5E74AB5
Procedure: RNAV (GPS) RWY 32 AMDT 1		Enroute: NO	Specialist: Smart, Phillip		Agreement Number:
Airport ID: KSSF			Airport City: SAN ANTONIO		State: TX
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: PENDING AIRNAV DATA USED. CONTACT ROBERT HAMILTON 405-954-4608. FEDERAL AVIATION ADMINISTRATION. QUALITY 41 CHECKED QUALITY 10 CHECKED					


STINSON MUNI (KSSF)
SAN ANTONIO, TX
RNAV (GPS) RWY 32 A1
500K
FULL APP



STINSON MUNI (KSSF)
SAN ANTONIO, TX
RNAV (GPS) RWY 32 A1
100K
LNAV FINAL



STINSON MUNI (KSSF)
SAN ANTONIO, TX
RNAV (GPS) RWY 32 A1
100K
CIRCLING



STINSON MUNI (KSSF)
SAN ANTONIO, TX
RNAV (GPS) RWY 32 A1
500K
HILPT / MISSED HOLDING

CTC SAN ANTONIO APP WITHIN
20 NM ON 128.05 318.1

CANNON FLD (53T) (C)
HILPT/MISSED HOLDING GANLE TOWER (1049)
48-009224

JABLO UD [UD]