



LOC/DME I-CLL 110.55 Chan 42(Y)	APP CRS 346°	Rwy Ldg TDZE Apt Elev	6932 311 321
--	------------------------	-----------------------------	---

ILS or LOC RWY 35

EASTERWOOD FLD (CLL)

ADP or DME required for procedure entry. ADP or DME required for LOC only.	MALSR 	MISSED APPROACH: Climb to 2500 on I-CLL north course to DERRS INT/I-CLL 11.5 DME and hold.
 For inop ALS, increase S-ILS 35 Cat E visibility to 3/4 SM and S-LOC 35 Cat E visibility to 1 3/8 SM. ILS glideslope unusable for coupled approaches below 1050 feet MSL.		

ATIS 126.85	HOUSTON APP CON 134.3 360.85	EASTERWOOD TOWER ★ 118.5 (CTAF) 0 284.7	GND CON 128.7 284.7	UNICOM 122.95
-----------------------	--	---	-------------------------------	-------------------------



ELEV 321	D	TDZE 311
----------	----------	----------

