

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 10/02/2025	APWS Task ID: 4F6F7A78C323428A9205430A912500F5	APWS Project ID: 4F6DC7F7311D46248520D295C45D887E
Procedure: RNAV (GPS) RWY 19 AMDT 1B		Enroute: NO	Specialist: Bristow, Travis		Agreement Number:
Airport ID: KFQD			Airport City: RUTHERFORDTON		State: NC
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: ACTIVE AIRPORT AND RUNWAY USED. CLEARS NOTAM FDC 4/2234. RNAV (GPS) RWY 01 APPROACH IS BEING PROCESSED FOR FLIGHT CHECK. CIRCLING OBSTACLES CONCURRENT WITH RNAV (GPS) RWY 01 APPROACH. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT DAVID DANNER, AJV-A421, 405-905-5077. QUALITY 21 CHECKED QUALITY 38 CHECKED					

RNAV (GPS) RWY 19
RUTHERFORD COUNTY/MARCHMAN FLD (FQD)

MISSED APPROACH:
Climb to 3000 direct
EPOZI and hold.

UNICOM
122.8 (CTAF) **L**

