

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 06/12/2025	APWS Task ID: 5C797C38E0D443FC9B2B7948D4940F30	APWS Project ID: 1F0AEE45D2A4443BBF1FD76CBC7B87A0
Procedure: VOR RWY 17 ORIG A		Enroute: NO	Specialist: Smart, Phillip		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID: BWD	Facility Type: VOR_DME	Flight Inspection Remark Type:			
Procedure Comments: P NOTAM CLEARS T NOTAM 4/9324 Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021 Guidance for Procedural Changes Requiring Flight Inspection/Validation. CONTACT ROBERT HAMILTON 405-954-4608. FEDERAL AVIATION ADMINISTRATION. QUALITY 9 CHECKED BEGUE QUALITY 32 CHECKED Digitally signed by PABLO ORTIZ-JR Mar 18, 2025					

BROWNWOOD, TEXAS

AL-705 (FAA)




24305

VOR/DME BWD	APP CRS	Rwy Idg	5599
113.55	171°	TDZE	1387
Chan 82(Y)		Apt Elev	1387

VOR RWY 17
BROWNWOOD RGNL (BWD)

Rwy 17 helicopter visibility reduction below 3/4 SM NA. For inop ALS, increase VOR Cat A and D visibility to 1 7/8 SM.	MALS	MISSED APPROACH: Climbing right turn to 4000 direct BWD VOR/DME and hold, continue climb-in-hold to 4000.
---	---	---

AWOS-3 118.325	FORT WORTH CENTER 127.45 290.3	UNICOM 122.8 (CTAF)
-------------------	-----------------------------------	------------------------



BROWNWOOD, TEXAS
Orig 31OCT24

31°48'N-98°57'W

BROWNWOOD RGNL (BWD)
VOR RWY 17

SC-3, 31 OCT 2024 to 28 NOV 2024

SC-3, 31 OCT 2024 to 28 NOV 2024