

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 08/07/2025	APWS Task ID: 66163A3F907E4B33981A9E06E2E860B6	APWS Project ID: CFB8180331E94FE1BBBAE80189B958F5
Procedure: FIX COODY 3 OK US		Enroute: NO	Specialist: Hirst, Charles		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments: 8260-2 Revision to correct distance from RZC VORTAC to COODY from 110.28 to 71.34. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION FOR QUESTIONS CONTACT Robert Hamilton, MANAGER 405-954-4608</div> <div>QUALITY 29 CHECKED</div>					