

Flight Procedures Cover Page	Task Action: Amendment	Task Type: FIX	Estimated Chart Date: 01/25/2024	APWS Task ID: 6A1F87671085438DBD58990112D4A1DB	APWS Project ID: DB8C35B61C3B4C4088E0C6AD6D8AF703
Procedure: FIX TAKKY 2 AL US		Enroute: NO	Specialist: Shelton, Gale		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
<div>Procedure Comments:</div> <div>TAKKY FIX AMENDMENT</div> <div>CORRECTED FIX USE FACILITIES AND HP COURSES</div> <div>CONTACT MICHAEL GARRITY (405) 954-5602</div> <div>PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.</div> <div><div>09/20/2023</div><div>QUALITY 14 CHECKED</div></div>					