

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: 6E0F9F528F244080AD1D58AE12D65138	APWS Project ID: F41ADF2D459941C9961F99ADE4CD81BF
Procedure: RNAV (GPS) RWY 3 ORIG-D		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: KDNV			Airport City: DANVILLE		State: IL
Facility ID:	Facility Type:	Flight Inspection Remark Type:			

Procedure Comments:
Visibility Initiative (Garmin) - Update IAP visibility minimums IAW Order 8260.3, Chapter 3, Section 3-3. Visibility Minimums.

PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.

CONTACT: CASEY HILL (405) 954-0624.



DANVILLE, ILLINOIS

AL-5117 (FAA)




25331

APP CRS 030°	Rwy Ldg TDZE 6006 Apt Elev 674 697
------------------------	--

RNAV (GPS) RWY 3
VERMILION RGNL (DNV)

RNP APCH - GPS.	▼ Circling NA to Rwy 12 and 30. ▲ Rwy 3 helicopter visibility reduction below ¾ SM NA.	MISSED APPROACH: Climb to 2600 direct COSMA and hold.
-----------------	---	---

AWOS-3 119.275	CHAMPAIGN APP CON ★ 121.35 285.65	CLNC DEL 121.7	UNICOM 122.7 (CTAF) 0
--------------------------	---	--------------------------	---------------------------------



DANVILLE, ILLINOIS
Orig-C 30NOV23

40°12'N-87°36'W

RNAV (GPS) RWY 3
VERMILION RGNL (DNV)

EC-3, 19 FEB 2026 to 19 MAR 2026