

Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 11/27/2025	APWS Task ID: 7257A243FF964BBEAC1CE3B34CF590EA	APWS Project ID: 3A709B473B6D40E295A1165F460D9FA1
Procedure: RNAV (GPS) RWY 25L AMDT 1D		Enroute: NO	Specialist: Bruno, John		Agreement Number:
Airport ID: KDAB			Airport City: DAYTONA BEACH		State: FL
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: CANCEL. CONTACT ROBERT HAMILTON AJV-433, 405-954-4608. 8260-2 ORMOND BEAC VORTAC 06/27/2025: THIS IS A CORRECTED COPY OF THE FORM APPROVED ON 03/25/2025. FIX USE: ADDED ENROUTE Y185, DELETED ENROUTE Y585. QUALITY 16 CHECKED QUALITY 29 CHECKED					

APP CRS	Rwy Idg	3195
250°	TDZE	33
	Apt Elev	34

CANCEL

RNAV (GPS) RWY 25L
DAYTONA BEACH INTL (DAB)

RNP APCH-GPS.		MISSED APPROACH: Climb to 1700 direct TACUR and hold.
T Rwy 25L helicopter visibility reduction below ¾ SM NA.		

ATIS 132.875	DAYTONA APP CON 125.8 269.075	DAYTONA TOWER 120.7 257.8	GND CON 121.9 348.6	CLNC DEL 119.3
-----------------	----------------------------------	------------------------------	------------------------	-------------------

