

Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP	Estimated Chart Date: 07/11/2024	APWS Task ID: 763A48E3E8D54B64985B80836ABEC955	APWS Project ID: 2D0576F7DC29443BB26B19803D498771
Procedure: HI-ILS Y OR LOC Y RWY 13, AMDT 4E		Enroute: NO	Specialist: Hirst, Charles		Agreement Number:
Airport ID: KACY			Airport City: ATLANTIC CITY		State: NJ
Facility ID: PVO	Facility Type: ILS	Flight Inspection Remark Type:			

Procedure Comments:

Change the published Glideslope Angle from 3.04 to 3.00 degrees - See email attachments. Glideslope was published at 3.04 degrees in error.

PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION

FOR QUESTIONS CONTACT ERIC SUSKI, MANAGER : 405-954-7331

