


Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: 9B6C840ECF764306AA5A05A84567EA07	APWS Project ID: 09073755FDEA421196C57CC0E535B3BA
Procedure: RNAV (GPS) RWY 12 - ORIG-C		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: KEFT			Airport City: MONROE		State: WI
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: Visibility Initiative (Garmin) - Update IAP visibility minimums IAW Order 8260.3, Chapter 3, Section 3-3. Visibility Minimums. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT: CASEY HILL (405) 954-0624. QUALITY 6 SN 3/10/26 CHECKED QUALITY 41 CHECKED					

APP CRS	Rwy Idg	5000
121°	TDZE	1086
	Apt Elev	1086


RNAV (GPS) RWY 12
MONROE MUNI (EFT)

RNP APCH-GPS.	MISSED APPROACH: Climb to 3000 direct FALKN and on track 143° to DAVIS and hold.
---------------	--

AWOS-3 118.375	ROCKFORD APP CON 126.0 327.0	UNICOM 123.05 (CTAF) 0
-------------------	---------------------------------	---------------------------



ELEV 1086	TDZE 1086
-----------	-----------



Procedure Turn NA	ALOOOF	3000	IGOGY	2700	1.1 NM to RW12	RW12	3.04° TCH 40	6.1 NM	3.8 NM	1.1
CATEGORY	A	B	C	D						
LNAV MDA	1480-1	394 (400-1)	1480-1¼	394 (400-1¼)						
CIRCLING	1540-1 454 (500-1)	1640-1 554 (600-1)	1640-1½ 554 (600-1½)	1640-2 554 (600-2)						