

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 09/05/2024	APWS Task ID: 9FAA5B543B6D489194EF9528DB298811	APWS Project ID: D90901DA9864455EAD88AB58A32875CB
Procedure: RNAV (GPS) RWY 36 AMDT 1A		Enroute: NO	Specialist: Johnsen, Daniel		Agreement Number:
Airport ID: C35			Airport City: REEDSBURG		State: WI
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: Minor amendment using active data for C35 airport and runways. Cancels NOTAM FDC 3/5013. Contact Allan Will, AJV-A423, (405) 954-6103. QUALITY 41 CHECKED QUALITY 10 CHECKED					


WAAS CH 82727 W36A	APP CRS 360°	Rwy Idg TDZE 903 Apt Elev 906
--	------------------------	---

OLD

RNAV (GPS) RWY 36

REEDSBURG MUNI (C35)

RNP APCH.		MISSED APPROACH: Climbing right turn to 3500 direct DLL VORTAC. Continue climb-in-hold to 3500.	
▼ Procedure NA at night. ▲ Rwy 36 helicopter visibility reduction below 1 SM NA.			
AWOS-3PT 118.95	DLL AWOS-3 118.325	MADISON APP CON ★ 135.45 343.7	UNICOM 122.8 (CTAF) 0





WAAS CH 82727 W36A	APP CRS 360°	Rwy ldg TDZE 903 Apt Elev 906
--	------------------------	---

RNAV (GPS) RWY 36


REEDSBURG MUNI (C35)

RNP APCH: GPS		MISSED APPROACH: Climbing right turn to 3500 direct DLL VORTAC and hold , Continue climb-in-hold to 3500.	
▼ Procedure NA at night. ▲ Rwy 36 helicopter visibility reduction below 1 SM NA.			
AWOS-3PT 118.95	DLL AWOS-3 118.325	MADISON APP CON ★ 135.45 343.7	UNICOM 122.8 (CTAF) 0




WURVI		Visual Segment - Obstacles.		3500	DLL
3500		360°			
		CUKON			
		FETAD 2.8 NM to RW36			
		RW36			
		2500			
		1800			
		6.1 NM		2.1 NM	
		2.8 NM			
CATEGORY	A	B	C	D	
LP MDA	1560-1	657 (700-1)	NA		
LNAV MDA	1580-1	677 (700-1)	NA		
C CIRCLING	1600-1	694 (700-1)	NA		

MAPS FROM AMDT 1



MAPS FROM AMDT 1



MAPS FROM AMDT 1

