

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 05/14/2026	APWS Task ID: A813B3C6A42A42488C66900A4323CAA9	APWS Project ID: CA7F0A1AB1BC482FB882B68E0A9AF80C
Procedure: RNAV (GPS) RWY 32 AMDT 2B		Enroute: NO	Specialist: Young, Silvia		Agreement Number:
Airport ID: KFVE			Airport City: FRENCHVILLE		State: ME
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			

Procedure Comments:

ACTIVE DATA USED FOR KFVE AIRPORT AND RWYS.

CANCEL NOTAM FDC 5/4699.

RAISED ALTITUDES AT IF/IAF BIROW AND FOR TAA 224/10 CW 044/10 TO BIROW FROM 3000 TO 3400.

RAISED MISSED APRPOACH HOLDING ALTITUDE FROM 3100 TO 4100.

NEW CIRCLING CAT B OBSTACLE: "TOWER (23-000175) 471809N/0681652W".

CRC REMAINDER CHANGED TO "CDCBF23E".

CONTACT CASIMIR TABAKA 405.202.7857



