

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 10/29/2026	APWS Task ID: A9F92997F57C49EC8B94C70044876FA7	APWS Project ID: 15D81E77CFE24A828A895BB7A4B49BF0
Procedure: ILS OR LOC RWY 5 AMDT 4		Enroute: NO	Specialist: Raimi, Kamarudini		Agreement Number:
Airport ID: KTRI			Airport City: BRISTOL/JOHNSON/KINGSPORT		State: TN
Facility ID: BON	Facility Type: ILS	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: UTILIZED ACTIVE DATA FOR KTRI AIRPORT, RUNWAYS, I-BON, MOCCA NDB AND BOOIE NDB/LOM. REMOVED HOLSTON MOUNTAIN (HNV) DUE TO VOR MON. CONTACT ROBERT HAMILTON: AJV-A433, 405-954-4608. QUALITY 38 CHECKED QUALITY 37 CHECKED					

FIPC BASIC FORM						
PROCEDURE: ILS OR LOC RWY 5 AMDT 4			AIRPORT NAME: TRI-CITIES		AIRPORT ID: KTRI	SPECIAL CONTROL NO: AP-07-040-26
FAC ID: BON		CITY: BRISTOL/JOHNSON/KINGSPORT			ST: TN	ORIG CHART DATE: 10/29/2026
DFL TYPE: PROC/A	THIRD PARTY: ☐ YES	EST. TIME ON SITE: 0.4	REIMB. NUMBER: AC0721	PTS TASK ID: A9F92997F57C49EC8B94C70044876FA7		
PREFLIGHT NOTES						
REVIEWER:					DATE:	
COMMENTS:					CHECK ONE: ☐ FLT CK REQ ☐ NFCR ☐ REJECT	
						YES
					CPV COMPLETE? ☒ X ☐ NO	
PROCEDURE RESULTS						
INSPECTION DATE: 08/04/2026	CREW #: VN534	N #: N67	INSTRUMENT PROCEDURE STATUS: ☒ SAT ☐ SAT W/CHANGES ☐ UNSAT		ARINC CODING: ☐ SAT ☐ SAT/GOLD ☐ UNSAT	
FLIGHT INSPECTOR SIGNATURE: william m yingling @ 08/05/2026 14:10			PRINTED NAME: YINGLING, WILLIAM MARK			NOTAM INITIATED? ☐ YES ☒ NO
FLIGHT INSPECTOR REMARKS: Complete SAT						
IN-FLIGHT OBSTACLE REPORT						
OBSTRUCTION ID #:	COORDINATES OR LOCATION:	GNSS ALTITUDE (MSL):	BAROMETRIC ALTITUDE (MSL):	HEIGHT ABOVE GROUND LEVEL:		

