


Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 08/07/2025	APWS Task ID: AC70E7BC13554B57815E8E94455783A5	APWS Project ID: FE7AD352E2164CF59A9260B25C5CC12F
Procedure: LOC RWY 4 AMDT 1		Enroute: NO	Specialist: Heiderstadt, Nicholas		Agreement Number:
Airport ID: KCJR			Airport City: CULPEPER		State: VA
Facility ID: DZH	Facility Type: LOC	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: DME Install ACTIVE DATA USED CONTACT JOHN BORDY 405-954-0980 QUALITY 38 CHECKED QUALITY 34 CHECKED					

LOC/DME I-DZH	APP CRS	Rwy Idg	5000
109.95	038°	TDZE	316
Chan 36 (Y)		Apt Elev	316


LOC RWY 4
CULPEPER RGNL (CJR)


DME required.	MISSED APPROACH: Climb to 900 then climbing left turn to 2600 on heading 180° and GVE VORTAC R-028 to NISAE/GVE 22.9 DME and hold.
Rwy 4 helicopter visibility reduction below 3/4 SM NA.	

AWOS-3 119.325	POTOMAC APP CON 128.525 306.925	CLNC DEL 121.6	UNICOM 123.075 (CTAF) 0
-------------------	------------------------------------	-------------------	----------------------------



LOC RWY 4
CULPEPER RGNL (CJR)





LOC BERWA to KCJR:RW04:AER TREE (416)
51-023675

NISAE to RACOP TERRAIN+AAO (968)
TP1733872

Missed Level Surface TERRAIN+AAO (985)
TP1973198

GVE:VORTAC to NISAE TOWER (1457)
51-000197

NISAE1_1 TOWER (1457)
51-000197

LOC RACOP to BERWA TERRAIN+AAO (561)
TP574

CULPEPER RGNL (CJR)
CULPEPER, VA
LOC RWY 4
AMENDMENT 1
1:500,000

CULPEPER RGNL (CJR)
CULPEPER, VA
LOC RWY 4
AMENDMENT 1
1:100,000
FINAL/MISSED

Missed Level Surface TERRAIN+AAO (985)
TP1973198

LOC BERWA to KCJR:RW04:AER TREE (416)
51-023675

LOC RACOP to BERWA TERRAIN+AAO (561)
TP574

Circling CAT A TERRAIN+VEG (593)
TP_CirclingCatA1701311

CULPEPER RGNL (CJR)
CULPEPER, VA
LOC RWY 4
AMENDMENT 1
1:100,000
CIRCLING