

Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP	Estimated Chart Date: 08/10/2023	APWS Task ID: BA0C646B61ED4DC093CC8A1F8E526B0A	APWS Project ID: 00A1C7CB20F04668A8A25B2869816382
Procedure: HI-ILS Z OR LOC Z RWY 8 AMDT 6A		Enroute: NO	Specialist: Russell, Todd		Agreement Number:
Airport ID: KJAX			Airport City: JACKSONVILLE		State: FL
Facility ID: JAX	Facility Type: ILS	Flight Inspection Remark Type:			
Procedure Comments: UTILIZED PENDING AIRNAV DATA FOR KJAX RWY 08. AMG VORMON - REMOVED ALL AMG VOR DEPENDENCIES. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT JASON KRETCHMER: AJV-A420, 405-954-4019 Digitally signed by JASON KRETCHMER May 19, 2023 QUALITY 10 CHECKED					

LOC I-JAX 110.7	APCH CRS 077°	Rwy Idg 10,000 TDZE 30 Arpt Elev 30
---------------------------	-------------------------	--


OLD

HI-ILS Z or LOC Z RWY 8


JACKSONVILLE INTL (KJAX)

DME required * When ALS inop, increase CAT E RVR to 40, vis to ¾ mile. ** When ALS inop, increase CAT E vis to 1¾ miles.	ALS-F-2 A	MISSED APPROACH: Climb to 1000 then climbing left turn to 4000 on heading 250° and on CRG R-316 to HAMOC/CRG 23 DME and hold, continue climb-in-hold to 4000.
--	--------------	---

ATIS 125.85	APP CON 119.0 269.9	TOWER 118.3 317.7	GND CON 121.9 348.6	CLNC DEL 119.5 290.275
-----------------------	-------------------------------	-----------------------------	-------------------------------	----------------------------------



ELEV 30	TDZE 30
---------	---------



CATEGORY	C	D	E
S-ILS 8 *	230/18	200	(200-½)
S-LOC 8 **	480/45	450	(500-¾)
CIRCLING	580-1½ 550 (600-1½)	580-2 550 (600-2)	760-2½ 730 (800-2½)

REIL Rwy 32	120	140	160	180	200
HIRL Rwy 8-26, 14-32	2:48	2:24	2:06	1:52	1:41
TDZL/CL Rwy 8-26, 14					

FAF to MAP 5.6 NM