

Print

Project Name: WYS UPDATE MINIMUMS AND MISSED

Project Reason: NEW EVALUATION RAISED S-ILS 1# MINS TO DA 6869/HAT 220 FOR PR ADDITION OF 19FT, LOC MINS NEW CONTROLLER 7507 MSL AAO 43545.00N/1110948.00W . MISSED APPROACH UPDATED ALTITUDE BASED ON C-I-H EVALUATION OBSTACLE 10096 TERRAIN + PR 340 + 1000 - SA661 REQUIRES MISSED AND HOLDING AT 10800. UPDATED VARIOUS NOTES.

Last Updated By: Joseph Zeder

Last Updated At: 2026-02-26 11:57:07.227055

Status: Verified

!FDC **6/2001** WYS IAP YELLOWSTONE, WEST YELLOWSTONE, MT. ILS OR LOC RWY 1, AMDT 4B... S-ILS 1# DA 6869/HAT 220. S-LOC 1 MDA 7880/HAT 1231, CIRCLING CATS A/B/C MDA 7880/HAA1231. CHANGE MISSED APPROACH TO READ: CLIMB TO 9000, THEN CLIMBING RIGHT TURN TO 10800 DIRECT TARGY LOM AND HOLD, CONTINUE CLIMB-IN-HOLD TO 10800. "# MISSED APPROACH REQUIRES MINIMUM CLIMB OF 300 FEET PER NM TO 10800". DELETE NOTE: OBTAIN LOCAL ALTIMETER ON CTAf, WHEN NOT RECEIVED PROCEDURE NA. DELETE NOTE: VGSI AND ILS GLIDEPATH NOT COINCIDENT. DELETE PLANVIEW NOTE: # MISSED APPROACH REQUIRES MINIMUM CLIMB OF 300 FEET PER NM TO 10800. DELETE PROFILE NOTE: * LOC ONLY, DELETE ASTERISK AT LO LOM 9000. THIS IS ILS OR LOC RWY 1, AMDT 4C. 2602261157-PERM

Digitally signed by
CASIMIR L TABAKA
Mar 02, 2026

