

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 08/08/2024	APWS Task ID: C689ACF77BC94022AC7E6A1175A76C2F	APWS Project ID: C21EE863A36F42E0BFB3C691F5CF99AE
Procedure: RNAV (GPS) RWY 34 AMDT 2A		Enroute: NO	Specialist: Neidigh, Jon		Agreement Number:
Airport ID: KAMG			Airport City: ALMA		State: GA
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION INCREASED LPV VISIBILITY FROM 3/4 TO 7/8 DUE TO AIRPORT INFRASTRUCTURE CONTACT JOHN BORDY: 405-954-0980 PNOTAM: 4/3024 QUALITY 41 CHECKED QUALITY 32 CHECKED Digitally signed by PABLO ORTIZ-JR Apr 16, 2024					

OLD

ALMA, GEORGIA



23222

WAAS CH 70635 W34A	APP CRS 337°	Rwy Idg TDZE 196 Apt Elev 200
--	------------------------	---

RNAV (GPS) RWY 34
BACON COUNTY (AMG)

RNP APCH. ▼ Rwy 34 helicopter visibility reduction below ¾ SM NA. ▲ For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -4°C or above 54°C.	MISSED APPROACH: Climb to 2300 direct CUYAT and hold.
---	---

ASOS 118.325	JACKSONVILLE CENTER 127.575 269.025	UNICOM 122.7 (CTAF) 0
------------------------	---	---------------------------------



2300	CUYAT	VGSI and RNAV glidepath not coincident (VGSI Angle 3.00°/TCH 30°).			
*LNAV only		HGXOX 1.9 NM to RW34	HISEB 1800	JEKEK	4 NM Holding Pattern
1.1 NM to RW34		RW34	820	1800	GP 3.00° TCH 40
1.1		0.8	3.1 NM	6.9 NM	
CATEGORY	A	B	C	D	
LPV DA	452-¾		256 (300-¾)		
LNAV/VNAV DA	459-⅞		263 (300-⅞)		
LNAV MDA	560-1		364 (400-1)		
CIRCLING	720-1	520 (600-1)	1000-2¼ 800 (800-2¼)	1000-2½ 800 (800-2½)	

ALMA, GEORGIA
Amdt 2 05DEC19

31°32'N-82°30'W

BACON COUNTY (AMG)
RNAV (GPS) RWY 34

SE-4, 30 NOV 2023 to 28 DEC 2023

SE-4, 30 NOV 2023 to 28 DEC 2023