

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 12/30/2021	APWS Task ID: CA14CDEF55AC43C796BAE099CE2B178F	APWS Project ID: 565A24D0C2444A7098E8DB4826CC33AB
Procedure: RNAV (GPS) RWY 23 AMDT 2C		Enroute: NO	Specialist: Boone-walt, Rose		Agreement Number:
Airport ID: KCAE			Airport City: COLUMBIA		State: SC
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: PNOTAM CIRCLING RADII INCREASE CONTACT: JASON KRETSCHMER AJV-A421 LEAD: 405.954.4019 <i>Digitally signed by</i> JASON KRETSCHMER Nov 08, 2021 <i>Digitally signed by</i> MARY MCDONALD Sep 28, 2021					



WAAS CH 40026 W23A	APP CRS 232°	Rwy Idg 7001 TDZE 213 Apt Elev 236
--	------------------------	---






RNAV (GPS) RWY 23

T

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -15°C (5°F) or above 48°C (118°F). DME/DME RNP-0.3 NA. Rwy 23 helicopter visibility reduction below $\frac{3}{4}$ SM NA.

MISSED APPROACH: Climb to 2300 direct EDURE and hold.

ATIS 120.15	COLUMBIA APP CON 133.4 285.6 (290°-109°) 124.15 338.2 (110°-289°)		COLUMBIA TOWER 119.5 257.8	GND CON 121.9 348.6	CLNC DEL 119.75
----------------	---	--	-------------------------------	------------------------	--------------------





CAE
COLUMBIA MUNI
COLUMBIA, SC
CIRC

Circling CAT C/D TOWER (679)
45-000971

Circling CAT A TREE (429)
45-023444

Circling CAT B TOWER (545)
45-001935

