

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: SID	Estimated Chart Date: 06/12/2025	APWS Task ID: D8861CA4893D4E3CBEE0CA6480F5EF9F	APWS Project ID: 64ECA26FC3EA42F785F9456B5164B37D
Procedure: ALNIC ONE DEPARTURE (RNAV)		Enroute: NO	Specialist: Hirst, Charles		Agreement Number:
Airport ID: ME50			Airport City: MILLINOCKET		State: ME
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			

**Procedure Comments:**  
SPECIAL SID.

Develop SID for ME50, MILLENOCKET, ME; for Helicopter Air Ambulance use only to allow for direct access to and from low-level ZK411 to the southeast. The helipad is far enough from the 14 CFR Part 97 approach that VFR weather minimums are required to transition to the IDF.

For additional questions contact Robert Hamilton, Manager 405-954-4608


awaiting FIG. do not send to FC until incorporated into this S file.

QUALITY  
21  
CHECKED

QUALITY  
38  
CHECKED

FIG PLACEHOLDER

MILLINOCKET RGNL  
MILLINOCKET, ME  
ME50  
COPTER ALNIC (RNAV) SID  
1:500,000



IDF Altitude Controller TOWER (798)  
23-000282

SPECIAL MILITARY ACTIVITY  
FOR IR850, IR851, IR852 CTC BANGOR RADIO  
ON 122.6 FOR ACTIVITY STATUS

LINCOLN RGNL (LRF)  
208 °L 28 122.8  
178 - 24 122.8

SPECIAL MILITARY ACTIVITY  
FOR IR850, IR851, IR852 CTC BANGOR RADIO  
ON 122.6 FOR ACTIVITY STATUS

SPECIAL MILITARY ACTIVITY  
FOR IR850, IR851, IR852 CTC BANGOR RADIO  
ON 122.6 FOR ACTIVITY STATUS

MILLINOCKET RGNL  
MILLINOCKET, ME  
ME50  
COPTER ALNIC (RNAV) SID  
1:100,000

