Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP		APWS Task ID: E9EE8D2A0E094259A294A5C3E13F4B71	APWS Project ID: 440CFA2977C84BD1A0EAB18F755021F0
Procedure: ILS OR LOC RWY 3 AMDT 1C		Enroute: NO	Specialist: Smart, Phillip		Agreement Number:
Airport ID: KCHO			Airport City: CHARLOTTESVILLE		State: VA
Facility ID:	Facility Type:	Flight Inspection Remark Type:			

## **Procedure Comments:**


Corrected the VOR radial on the alternate missed approach instructions.



Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021 Guidance for Procedural Changes Requiring Flight Inspection/Validation

CONTACT MR. ROBERT HAMILTON, MANAGER AJV-A433 AT 405-954-4608. FEDERAL AVIATION ADMINISTRATION.

AL-765 (FAA)



1100-1

**C** CIRCLING

NE-3,

03 JAN

2019

Ö

 $\omega$ 

**JAN 2019** 

Knots

1500-21/2

860 (900-21/2)

460 (500-1)

1500-23/4

860 (900-23/4)

6:00 | 4:00 | 3:00 | 2:24 | 2:00

120 | 150

FAF to MAP 6 NM

90

60