


Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 12/26/2024	APWS Task ID: EC7147213285462786CF13CD53BBBBBA3	APWS Project ID: 66BA306583964081868E1BEF6B20BF44
Procedure: RNAV (GPS) RWY 29 ORIG		Enroute: NO	Specialist: Wilkinson, Christopher		Agreement Number:
Airport ID: KRVJ			Airport City: REIDSVILLE		State: GA
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: ACTIVE DATA USED FOR KRVJ AIRPORT AND RUNWAYS. CONTACT CASIMIR TABAKA, AJV-A430, 405-202-7857 QUALITY 38 CHECKED QUALITY 10 CHECKED					


FIG

SWINTON SMITH FLD AT REIDSVILLE MUNI (RVJ)

MISSED APPROACH: Climb to 3000 direct FEVNA and hold, continue climb-in-hold to 3000.

CTAF
122.9 **L**


TDZE 196





SWINTON SMITH FLD AT REIDSVILLE MUNI (RVJ)


32°04'N-82°09'W


RNAV (GPS) RWY 29














AIRPORT ID: KRVJ
AIRPORT NAME: SWINTON FLD AT
REIDSVILLE MUNI
CITY/STATE: REIDSVILLE, GA
PROC ID: RNAV (GPS) RWY 29
ORIG
SCALE: 1:500,000
TAA RB

TAA RB 114 CW 204
TOWER (892)
13-020234

COASTAL MOA ADVISORY SERVICE
VHF 19.225 OR PHONE 1-800-229-2839

