

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: F1E9DB5604EA4E9FA483797B27E8EE77	APWS Project ID: 45C3FA10DF3B4E9D81326D7B5B168942
Procedure: ILS OR LOC RWY 10 AMDT 2A		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: KLAL			Airport City: LAKELAND		State: FL
Facility ID: LAL	Facility Type: ILS	Flight Inspection Remark Type:			

Procedure Comments:

Visibility Initiative (Garmin) - Update IAP visibility minimums IAW Order 8260.3, Chapter 3, Section 3-3. Visibility Minimums.

PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.

CONTACT: CASEY HILL (405) 954-0624.



