

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 04/20/2023	APWS Task ID: F40FB1FD08034CBE95AC9498E8835AA0	APWS Project ID: E0CC0E7FB97640C5B8D1EB63DB02FBFF
Procedure: ILS Y OR LOC Y RWY 26 AMDT 0E		Enroute: NO	Specialist: Hanby, William		Agreement Number:
Airport ID: KCSV			Airport City: CROSSVILLE		State: TN
Facility ID: CSV	Facility Type: ILS	Flight Inspection Remark Type:			
<p>Procedure Comments: This cancels T NOTAM 2/9233 PENDING DATA UTILIZED. APT ELEV CHANGED FROM 1881 TO 1882. S-ILS 26 DA/HAT CHANGED FROM 2090/219 TO 2121/250, INCREASE S-ILS 26 VIS FROM 3/4 TO 1 SM - OCS PENS; CHANGED CIRCLING HAAS ALL CATS - AIRPORT ELEVATION CHANGE - NEW SURVEY DATA. PROCEDURE NA AT NIGHT AND RWY 26 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED - 20:1 PENETRATIONS EXIST RW 08/26 - NEW SURVEY DATA. AIRPORT HAS AN ON-GOING OBSTACLE CLEARING PROJECT WITH ESTIMATED COMPLETION DATE JUNE 2023. REMOVED NOT COINCIDENT NOTE - NEW SURVEY, VGSI AND ILS GLIDEPATH/TCH NOW COINCIDENT. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION CONTACT MR. CASIMIR L. TABAKA, IFP Team 3, Sub-Team B, AJV-A432 at 405-954-7931.</p>					

