

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 11/04/2021	APWS Task ID: F7D6D30FAB154BF782FEF201505F8B00	APWS Project ID: BCF643B1083245C8A3AA8068E3EA5D38
Procedure: RNAV (GPS) RWY 36 AMDT 1C		Enroute: NO	Specialist: Miller, Ralph		Agreement Number:
Airport ID: KFDY			Airport City: FINDLAY		State: OH
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: P-NOTAM. ORDER 8260.3, CHAPTER 2, NEW CIRCLING CRITERIA APPLIED ACTIVE DATA USED. CONTACT JASON KRETSCHMER, AJV-A421, 405-954-5077. <i>Digitally signed by</i> JASON KRETSCHMER Sep 01, 2021  					

WAAS CH 72705 W36A	APP CRS 005°	Rwy Idg TDZE 809 Apt Elev 813
--	------------------------	---

OLD

RNAV (GPS) RWY 36

FINDLAY (F'DY)

RNP APCH

▼ For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 47°C.
Baro-VNAV and VDP NA when using Lima Allen County altimeter setting.
When local altimeter setting not received, use Lima Allen County altimeter setting: increase all
DAs/MDAs 80 feet; increase LNAV Cat C/D visibility 1/8 SM and Circling Cat C/D visibility 1/4 SM.

MISSED APPROACH:
Climb to 2500 direct
GAVEY and hold.

ASOS 132.85	TOLEDO APP CON 120.8 317.55	UNICOM 122.725 (CTAF) 0
-----------------------	---------------------------------------	-----------------------------------



