



DP	TAKEOFF MINIMUMS	5	KRDM	REDMOND	OR (US)
DP	SALEM		KSLE	SALEM	OR (US)
DP	TAKEOFF MINIMUMS		S21	SUNRIVER	OR (US)
EN ROUTE	J159				(US)
EN ROUTE	T261				(US)
EN ROUTE	V121				(US)
EN ROUTE	V165				(US)
EN ROUTE	V25				(US)
EN ROUTE	V269				(US)
EN ROUTE	V536				(US)
EN ROUTE	V595				(US)
IAP	RNAV (GPS) RWY 34	2	KBDN	BEND	OR (US)
IAP	RNAV (GPS) Z RWY 16		KBDN	BEND	OR (US)
IAP	VOR RWY 16	4	KBDN	BEND	OR (US)
IAP	RNAV (GPS) RWY 11	3	S39	PRINEVILLE	OR (US)
IAP	RNAV (GPS) RWY 29	3	S39	PRINEVILLE	OR (US)
IAP	ILS OR LOC RWY 23		KRDM	REDMOND	OR (US)
IAP	JUNIPER VISUAL RWY 23		KRDM	REDMOND	OR (US)
IAP	RNAV (GPS) Y RWY 29		KRDM	REDMOND	OR (US)
IAP	RNAV (GPS) Z RWY 29		KRDM	REDMOND	OR (US)
IAP	VOR-A	5	KRDM	REDMOND	OR (US)
IAP	RNAV (GPS) RWY 18		S21	SUNRIVER	OR (US)

**REQUIRED CHARTING:** DP, IAP, EN ROUTE LOW, EN ROUTE HIGH, CONTROLLER LOW, CONTROLLER HIGH

**COMPULSORY REPORTING POINT:** NO

**RECORD REVISION NUMBER:** 31

**DATE OF REVISION:** 01/22/2026

**REASON FOR REVISION:**

1. PATTERNS: REV 30 PAT 1 PATTERN NUMBER UPDATED TO PAT 5 AND HOLDING MIN CHANGED TO 6100.
2. PATTERNS: REV 30 PAT 2 PATTERN NUMBER UPDATED TO PAT 1.
3. PATTERNS: REV 30 PAT 3 PATTERN NUMBER UPDATED TO PAT 2.
4. PATTERNS: REV 30 PAT 4 PATTERN NUMBER UPDATED TO PAT 3.
5. PATTERNS: REV 30 PAT 5 PATTERN NUMBER UPDATED TO PAT 4.
6. PROCEDURES REQUIRING CLIMB-IN-HOLD: ADDED VOR-A AT KRDM.
7. CONTROLLING OBSTRUCTIONS: PAT 3 UPDATED CONTROLLER FOR 230 PATTERN AIRSPEED.
8. CONTROLLING OBSTRUCTIONS: PAT 5 UPDATED CONTROLLERS FOR BOTH 230 AND 310 PATTERN AIRSPEEDS.
9. FIX USE: REMOVED RNAV (RNP) Z RWY 23 PROCEDURE AT KRDM.

<b>INITIATED BY:</b>	<b>DATE:</b>	<b>ORGANIZATION:</b>	<b>NAME:</b>
<b>OFFICE OF PRIMARY RESPONSIBILITY:</b>		AJV-A433	<b>NAME:</b> BRYANT SMITH
<b>APPROVED BY:</b>	<b>DATE:</b> 12/18/2025	<b>OFFICE:</b> AJV-A443	<b>NAME:</b> ROBERT HAMILTON
	<b>SIGNATURE:</b>		



# RADIO FIX AND HOLDING DATA RECORD

NAME: HORRN

STATE: OR

COUNTRY: US

ICAO REGION CODE: K1

LATITUDE/LONGITUDE: 442851.03N/1213832.73W

TYPE: WP, DME

AIRSPACE DOCKET:

FIX TYPE OF ACTION: NO CHANGE

## FIX MAKE-UP FACILITIES:

FAC	NAME	IDENT	TYPE	CLASS	MAG BRG	TRUE BRG	DME	DIST FROM FAC NM	FAC FEET	MRA	MAA
1	DESCHUTES	DSD	VORTAC	VH	295.29	313.29	20.02	20.00		12500	17500

HOLDING:

HOLDING TYPE OF ACTION: NO CHANGE

## FIX USE:

USE TYPE	USE TITLE	FAC	PAT	AIRPORT IDENT	CITY	STATE
EN ROUTE	V165	1				(US)
IAP	RNAV (GPS) Y RWY 16			KBDN	BEND	OR (US)
IAP	VOR RWY 16	1		KBDN	BEND	OR (US)
IAP	RNAV (GPS) RWY 11			S39	PRINEVILLE	OR (US)
IAP	RNAV (GPS) Y RWY 23			KRDM	REDMOND	OR (US)
IAP	RNAV (GPS) Y RWY 5			KRDM	REDMOND	OR (US)
IAP	VOR-A	1		KRDM	REDMOND	OR (US)

REQUIRED CHARTING: IAP, EN ROUTE LOW, CONTROLLER LOW

COMPULSORY REPORTING POINT: NO

RECORD REVISION NUMBER: 4

DATE OF REVISION: 08/10/2023

## REASON FOR REVISION:

1. FIX MAKE-UP: UPDATED DME FROM 20.00 TO 20.02.
2. FIX USE: UPDATED KBDN USE TITLE FROM "VOR/DME RWY 16" TO "VOR RWY 16".
3. FIX USE: UPDATED AIRPORT IDENT FROM KS39 TO S39.

INITIATED BY:

DATE:

ORGANIZATION:

NAME:

OFFICE OF PRIMARY RESPONSIBILITY:

AJV-A423

NAME: PATRICK COMBS

APPROVED BY:

DATE: 08/10/2023

OFFICE: AJV-A420

NAME: MARLON ROBINSON

SIGNATURE:

