

**Federal Aviation
Administration**

Transmittal Letter 20-15

May 29, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/16/2020	FL	Tallahassee	Tallahassee Intl	0/9492	5/13/2020	VOR RWY 18, Amdt 12B

AIRAC Date: 16 JULY 2020

FDC 0/9492 TLH IAP TALLAHASSEE INTL, TALLAHASSEE, FL. VOR RWY 18, AMDT 12B... CHART
CIRCLING ICON. CIRCLING CAT D MDA 800/HAA 717. WAPIM FIX MINIMUMS; CIRCLING CAT B MDA
600/HAA 517, CAT C MDA 640/HAA 557, CAT D MDA 800/HAA 717, VIS 2 1/4. DELETE ALTIMETER
SETTING NOTE. THIS IS VOR RWY 18, AMDT 12C. 2005081736-PERM