

**Federal Aviation
Administration**

Transmittal Letter 22-20

August 5, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
9/8/2022	IL	Chicago/Au rora	Aurora Muni	2/9929	7/20/2022	VOR RWY 36, Amdt 3A

AIRAC Date: 8 SEPTEMBER 2022

FDC 2/9929 ARR IAP AURORA MUNI, CHICAGO/AURORA, IL. VOR RWY 36, AMDT 3A...
COAST FIX MINIMUMS: CIRCLING CAT C MDA 1300/HAA 588. THIS IS VOR RWY 36, AMDT
3B. 2204191910-PERM