

**Federal Aviation
Administration**

Transmittal Letter 21-05

JANUARY 8, 2021

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
2/25/2021	VT	Barre/Montpelier	Edward F Knapp State	0/9161	1/4/2021	ILS OR LOC RWY 17, Amdt 7A

25 FEBRUARY 2021

FDC 0/9161 MPV IAP EDWARD F KNAPP STATE, BARRE/MONTPELIER, VT. ILS OR LOC RWY 17, AMDT 7A... DELETE ALTERNATE MISSED APPROACH. THIS IS ILS OR LOC RWY 17, AMDT 7B. 2012291700-PERM