

**Federal Aviation
Administration**

Transmittal Letter 22-15

MAY 27, 2022

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
7/14/2022	VT	Barre/Mont pelier	Edward F Knapp State	2/4505	3/16/2022	ILS OR LOC RWY 17, Amdt 7B

AIRAC Date: 14 JULY 2022

FDC 2/4505 MPV IAP EDWARD F KNAPP STATE, BARRE/MONTPELIER, VT. ILS OR LOC RWY 17, AMDT 7B...
CHART NOTE: VGSI AND ILS GLIDEPATH NOT COINCIDENT (VGSI ANGLE 3.00/TCH 46). THIS IS ILS OR
LOC RWY 17, AMDT 7C. 2203151903-PERM