

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 15-25

October 23, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION.....						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
10-Dec-15	KS	Topeka	Forbes Field	5/4401	10/19/15	VOR/DME OR TACAN RWY 3, Amdt 6A

FDC 5/4401 FOE IAP FORBES FIELD, TOPEKA, KS. VOR/DME OR TACAN
RWY 3, AMDT 6A... CIRCLING CAT A HAA 442, CAT B-C HAA 502, CAT D MDA
1700/HAA 622. AIRPORT ELEVATION 1078. CHART CIRCLING ICON.

THIS IS VOR/DME OR TACAN RWY 3, AMDT 6B. 1510091719-PERM