

**Federal Aviation
Administration**

Transmittal Letter 16-09

March 11, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
28-Apr-16	ID	Twin Falls	Joslin Field - Magic Valley Rgnl	5/7334	02/24/16	VOR RWY 8, Amdt 5

AIRAC Date: 28 APRIL 2016

FDC 5/7334 TWF IAP JOSLIN FIELD - MAGIC VALLEY RGNL, TWIN FALLS, ID. VOR RWY 8, AMDT 5... S-8 HAT 911 ALL CATS.. CHART TDZE 4149 DELETE THRE 4144. CHART NOTE: NIGHT LANDING: RWY 30 NA.. DELETE NOTE: CIRCLING TO RWY 30 NA AT NIGHT.. AZAJI FIX MINIMUMS S-8 HAT 491 ALL CATS.. THIS IS VOR RWY 8, AMDT 5A. 1512151956-PERM