U.S. Department of Transportation

Federal Aviation Administration

**Transmittal Letter 18-07** 

**February 9, 2018** 

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
29-Mar-18	СТ	Willimantic	Windham	7/1583	1/24/18	RNAV (GPS) RWY 27, Amdt 1A

AIRAC Date: 29 MARCH 2018

FDC **7/1583** IJD IAP WINDHAM, Willimantic, CT. RNAV (GPS) RWY 27, AMDT 1A... CHART NOTE: PROCEDURE NA AT NIGHT. CHART NOTE: RWY 27 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. CHART PROFILE NOTE: VISUAL SEGMENT- OBSTACLES. DELETE NOTE: WHEN VGSI INOP, STRAIGHT-IN/CIRCLING RWY 27 PROCEDURE NA AT NIGHT. DELETE NOTE: CIRCLING TO RWY 09, 18, 36 NA AT NIGHT. DELETE NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NA. DELETE: DESCENT ANGLE 3.00/TCH 40. DELETE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT. THIS IS RNAV (GPS) RWY 27, AMDT 1B. 1711221449-PERM