

**Federal Aviation
Administration**

Transmittal Letter 12-08

March 2, 2012

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
5-Apr-12	AZ	Phoenix	Phoenix Sky Harbor Intl	2/8151	2/27/12	ILS OR LOC RWY 25L, AMDT 1E

AIRAC Date: 5 APRIL 2012

FDC 2/8151 PHX FI/P IAP PHOENIX SKY HARBOR INTL, PHOENIX, AZ. ILS OR LOC
RWY 25L, AMDT 1E... S-ILS 25L DA 1326/HAT 200 ALL CATS. DELETE PLANVIEW
NOTE: RADAR REQUIRED FOR SIMULTANEOUS APPROACHES. CHART NOTE:
SIMULTANEOUS APPROACH AUTHORIZED WITH RWY 26. THIS IS ILS OR LOC RWY
25L, AMDT 1F.