

**Federal Aviation
Administration**

Transmittal Letter 20-24

October 2, 2020

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/5/2020	WA	Seattle	Boeing Field/King County Intl	0/4645	9/16/2020	ILS OR LOC RWY 14R, Amdt 31A

AIRAC Date: 5 NOVEMBER 2020

FDC 0/4645 BFI IAP BOEING FIELD/KING COUNTY INTL, SEATTLE, WA. ILS OR
LOC RWY 14R, AMDT 31A... DELETE NOTE: S-ILS 14R # PROCEDURE NA WHEN
VGSI INOP. CHART NOTE: S-ILS 14R # MINIMUMS NA WHEN VGSI INOP. THIS IS
ILS OR LOC RWY 14R, AMDT 31B. 2008191854-PERM