Federal Aviation Administration

**Transmittal Letter 23-17** 

June 23, 2023

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVEUPONPUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
8/10/2023	TN	Knoxville	Mc Ghee Tyson	3/4228	6/1/2023	ILS OR LOC RWY 23L, Orig

## AIRAC Date: 10 AUGUST 2023

FDC 3/4228 TYS IAP MC GHEE TYSON, KNOXVILLE, TN. ILS OR LOC RWY 23L, ORIG... DELETE APT ELEV 981. CHART APT ELEV 986. CIRCLING CAT A HAA 514, CAT B HAA 634, CAT C HAA 674, CAT D HAA 914. DELETE PROFILE NOTE: \*LOC ONLY. DELETE ASTERISK FROM VDP AT I-OXH 2.55 DME. DELETE ASTERISK NEXT TO STEPDOWN FIX XEKEF ALTITUDE 1800 IN PROFILE VIEW. DELETE NOTE: DME REQUIRED. DELETE PLANVIEW NOTE: DME OR RADAR REQUIRED. EQUIPMENT REQUIREMENTS NOTE: DME OR RADAR REQUIRED. THIS IS ILS OR LOC RWY 23L, ORIG-A. 2306011400-PERM